


जा.क्र.सा.बां.उपवि/पलूस/ ६२७ / २०२४
उपविभागीय अधिकारी (स्थापत्य)
सा.बां.उपाविभाग,पलूस यांचे कार्यालय
ता.पलूस जि.सांगली
दिनांक :- २७/०६/२०२४

BUILDING STABILITY CERTIFICATE

This is to Certified that the existing building **Vikas Charitable Trust's, "Kirloskar High School & Junior College at Kirloskarvadi"** CTS No 437,438 at **Kundal & Gat No 903 at Sawantpur Tal Palus, Dist.- Sangli**, have 8 building blocks occupied by **Kirloskar High School & Junior College at Kirloskarvadi** have complied with the Building safety requirements in accordance with National Building code Rules, 2005 & 2016 and verified by the officers concerned of Maharashtra Public Works Department on **Date 26/06/2024** in the presence of Mr.M.S.Patil Sub Divisional Officer (Civil) P.W.Sub Division Palus & Mr.D.V.Mane Assistant Engineer Gr-II P.W.Sub Division Palus also Mr.DattaPrasad Mithari, Principal and that the building is fit for occupancy upto classes V to X with effect from **Date 27/06/2024** for a period of **One year** in accordance with rule and subject to compliance of the specific conditions as appended.

This stability certificate is issued on request letter of Trustee, Vide Letter Dtd.29/05/2024 Vikas Charitable Trust A/P-Kirloskarvadi Tal.Palus Dist.Sangli for CBSE Board affiliation Purpose with reference to Drawings attached & cerified by Kanitkar & Kulkarni (Structural Consultants & Chartered Engineers), Kothrud Pune Vide Letter Dtd.05/06/2024

1. Building 1 – (G + 1 load Bearing Structure)
 - Toilet door & dado Tiles should be replaced.
 - Dampness in staircase should be cured.
2. Building 2 – (Ground Floor load Bearing Structure)
 - Replace Damaged Eaves Board.
3. Building 3 – (Ground Floor load Bearing Structure)
4. Building 4 – Work Shop
 - Replace Damaged AC Sheets.
5. Building 5 – (Play Group)
 - Replace Damaged Door.
6. Building 6 ,7 & 8


Sub Divisional Officer (Civil)
P.W.Sub Division Palus


Principal
Kirloskar High School &
Jr. College, Kirloskarvadi.
416308