

जा.क्र.सा.बां.उपवि/पलूस/ ECU /२०२५
उपविभागीय अधिकारी (स्थापत्य) सा.बां.
उपविभाग, पलूस यांचे कार्यालय
ता. पलूस जि. सांगली
दिनांक :- १९/०८/२०२५

BUILDING STABILITY CERTIFICATE

This is to Certified that the existing building Vikas Charitable Trust's, "Kirloskar High School at Kirloskarwadi" CTS No 437,438 at Kundal & Gat No 903 at Sawantpur Tal.Palus Dist.Sangli have 8 building blocks occupied by "Kirloskar High School at Kirloskarwadi" have complied with the Building safety requirements in accordance with National Building code Rules 2005 & 2016 & verified by the officers concerned of Maharashtra Public Works Department on Date 14/08/2025 in the presence of Mr..M.S.Patil Sub Divisional Officer (Civil) P.W.SubDivision,Palus & Mr.D.V.Mane Assistant Engineer GrII P.W.SubDivision, Palus also Mr.U.B.Kulkarni, Principal & that the building is fit for occupancy upto classes I to X with effect from Date: 19/08/2025 for a period of **One Year** in accordance with rule & subject to compliance of the specific conditions as appended.

This stability certificate is issued on request letter of Trustee, Vide Leuer Did 11/08/2025 Vikas Charitable Trust's, A/P-Kirloskarwadi Tal, Palus Dist. Sangli for CBSE Board Mitation Purpose with reference to Drawings attached & cerified by Kanitkar & Kulkarni (Structural Consultants & Chartered Engineers) Kothurd Pune Vide Letter Dtd 03/06/2025

1. Building 1 (G+1 load Bearing Structure)

- ❖ Toilet door & dado Tiles should be replaced.
- ❖ Dampness in staircase should be cleared.

2. Building 2: (Ground Floor load Bering Structure)

- ❖ Replace Damaged Eaves Board.


3. Building 3: (Ground Floor load Bearing Structure)

4. Building 4: (Work Shop)

- ❖ Replace Damagae AC Sheets.

5. Building 5- (Play Group) Replace Damage Door.

6. Building 6,7 & 8


(M.S. Patil)
Sub Divisional Officer (Civil)
P.W.Sub Division, Palus